



Replacement Hill-Rom Bed Casters & Wheels by Tente

BUY 11 GET 1 FREE!



Tente Original Equipment Exact Replacement



Red Top, 8" Total Lock
Hill-Rom 9022910
Long Stem
AL-18576L



8" Stretcher Wheel
Pressed Steel Center, Black
Polyurethane Tread, Precision Bearing
AL-18602



5" Grey Polyurethane Wheel
With Precision Ball Bearing for
standard Hill-Rom Beds.
Hill-Rom SA7081
Grey
AL-41500 \$14.95 Each
Light Neutral
AL-63090 \$14.95 Each



Green Top, 8" Steer Lock
Hill-Rom 9022918
Short Stem, Black Wheel
AL-18568HS



EP2

Hill-Rom Bed Model	Caster Description	Hill-Rom Part No.	Hill-Rom Part No.	ALCO Part No.	Price Each
With Precision Fork Bearings					
3600-3606 Birthing Bed	6" swivel w/1" solid stem	450846048		AL-50744MM	\$69.95
Affinity Bed	6" steer lock (central lock)	450846448		AL-50738HN	\$119.95
	6" total lock (central lock)	450846648		AL-50741HN	\$118.95
880-886 CCU/Century CC	8" steer lock (central lock) Long stem	9022911	SA1484	AL-18568L	\$119.95
892-896 GPS	8" total lock (central lock) Long stem	9022910	SA1483	AL-18576L	\$118.95
	8" steer lock (central lock) Long stem	9022909	SA1351	AL-18568L	\$119.95
	8" total lock (central lock) Long stem	9022908	SA1350	AL-18576L	\$118.95
ICU	8" steer lock (central lock) Long stem (Anti-Static)	9022915		AL-18566L	\$119.95
	8" total lock (central lock) Long stem (Anti-Static)	9022914		AL-18574L	\$118.95
8030, 8020, 8010 Transtar stretcher	8" steer lock (central lock) Short stem (Green Top, Grey Poly Wheel)	9022918		AL-50739HS	\$118.95
	8" total lock (central lock) Short stem (Red Top, Grey Poly Wheel)	9022919		AL-50742HS	\$118.95
	5" wheel in middle of bed (for support)	143076		AL-68986	\$29.95
Durastar stretcher	8" steer lock (central lock) Short stem (Green Top, Black Wheel)	9022918		AL-18568HS	\$119.95
	8" total lock (central lock) Short stem (Red Top, Black Wheel)	9022919		AL-18576HS	\$118.95
Total Care* Advanta	5" Steer Lock (Central Lock) Short Stem	6390602		AL-57602HS	\$129.95
Bariatric Plus	5" Total Lock (Central Lock) Short Stem (Casters Made With Plastic Shroud)	6390601		AL-57605HS	\$129.95
Total Care** Intellidrive	6" Steer Lock (Central Lock) Short Stem	6831003		AL-57603HS	\$169.95
	6" Total Lock (Central Lock) Short Stem (Casters Made With Plastic Shroud)	6831002		AL-57606HS	\$169.95
Basic Care Bed*** with 6" casters (See Note Below)	6" Steer Lock (Central Lock) Twin Wheel With Short Stem	9022924	4724002	AL-57615HS	\$189.95
	6" Total Lock (Central Lock) Twin Wheel With Short Stem	9022925	4724001	AL-57617HS	\$149.95
Resident Bed	5" Swivel w/7/16"x2" Grip Ring Stem (2 each)			AL-41469BE	\$32.95
	5" Total lock w/7/16"x2" Grip Ring Stem (2 each)			AL-41489BE	\$35.95
	3" Swivel w/7/16"x2" Grip Ring Stem (2 each)			AL-41467BE	\$16.95
	3" Total lock w/7/16"x2" Grip Ring Stem (2 each)			AL-41487BE	\$18.95
Recliner	3" Swivel 7/16 X 1-1/4" Grip Ring Stem	35142		AL-18504BA	\$17.95
	3" Total Lock (Toe Brake) 7/16 x 1-1/4" Stem	35143		AL-18536BA	\$20.95
	Plastic Socket Insert	35141		AL-69001	\$0.95
Long Term Care	3" Swivel 1" Solid Stem	D79X035		AL-18504MM	\$26.95
	3" Total Lock (Toe Brake) 1" Solid Stem	D79X034		AL-18536MM	\$33.95
Hill-Rom: Tente Replacement Wheels	5" Steel Center, Cone Bearing, Rubber Grey	4331501	SA3712	AL-18596	\$18.95
	5" Plastic Center, Precision Bearing, TPR Rubber Grey	N/A	N/A	AL-41499	\$14.95
	5" Plastic Center, Precision Bearing, Poly Grey	SA7081	N/A	AL-41500	\$14.95
	5" Plastic Center, Roller Bearing, Elastic Tire	143076	N/A	AL-68986	\$29.95
	6" Plastic Center, Precision Bearing, Poly Grey Tire	SA7113		AL-41501	\$24.95
	8" Plastic Center, Precision Bearing, Poly Grey Tire	SA8894		AL-41502	\$49.95
	8" Steel Center, Precision Bearing, Rubber Grey Tire	SA4382		AL-18600	\$49.95
	8" Steel Center, Precision Bearing, Poly Black Tire	SA4383		AL-18602	\$49.95
	8" Steel Center, Precision Bearing, Poly Red Tire			AL-18602R	\$49.95
	8" Precision Bearing, Black Conductive Tire (anti-static)			AL-18600C	\$49.95

*For beds manufactured 2000 to Present

**For beds manufactured 2005 to Present

***Note: On Basic Care Beds with 5" casters, these casters have extended height stems. All four casters must be replaced with 6" version.